












TS-550 SOFTWARE UPGRADE 1.8.22.8648

The Franklin Fueling Systems (FFS) TS-550 Software Upgrade Kit contains the latest release of software for the TS-550 Fuel Management System. This kit allows you to upgrade a TS-550 console to the current software release. This kit is intended to upgrade only TS-550 consoles. FFS recommends this upgrade.

COMPONENTS THAT CHANGED

Component	New Version		Prior Version
T5 Series Upgrade Software	1.8.22.8648		1.8.17.8544
Control Module	1.8.22.8648		1.8.17.8544
2-Wire Sensor Module	0.9.1		0.9.0

COMPONENTS THAT DID NOT CHANGE

Component	Current Version	
IO Module	0.9.1	
Printer Module	1.0.1	
AC Input Module	0.9.0	
4-20mA Module	1.0.8	
Relay Module	0.9.1	
Probe Module	1.1.9	
3-Wire Sensor Module	0.9.6	
Power Supply Module	1.2.2	



RELEASE NOTE

This software upgrade corrects an issue in which a sensor alarm that occurs and clears very quickly can cause a functional timing issue with other applications.